















STEP 7											
□ D.1或而資驗設計資驗設計(5-16)/HW6-4.4x7 - Design-Expert 7.0.0											
File Edit View Display Options Design Tools Help											
								完成7個步驟即完成軟體設定			
Notes for HW6-4.dx7		Std	Run	Block	Factor 1 A:A	Factor 2 B:B	0.0				
Graph Columns		1	10	Block 1	295.00	7.00	10.00	15.00	5		
- Craph Countris		2	4	Block 1	325.00	7.00	10.00	15.00	11		
Malysis		3	6	Block 1	295.00	9.00	10.00	15.00	3.5		
R1 (Analyzed)		4	3	Block 1	325.00	9.00	10.00	15.00	9		
L. Optimization	_	5	14	Block 1	295.00	7.00	20.00	15.00	0.5		
····) Numerical	_	6	8	Block 1	325.00	7.00	20.00	15.00	8		
Point Prediction	_	7	7	Block 1	295.00	9.00	20.00	15.00	1.5		
	—	8	2	Block 1	325.00	9.00	20.00	15.00	9.5		
	-	9	9	Block 1	295.00	7.00	10.00	30.00	8		
	-	10	16	Block 1	325.00 295.00	00.1	10.00	30.00	12.0		
		12	1	Block 1	325.00	9.00	10.00	30.00	15.5		
		13	5	Block 1	295.00	7.00	20.00	30.00	1		
		14	13	Block 1	325.00	7.00	20.00	30.00	6		
		15	15	Block 1	295.00	9.00	20.00	30.00	5		
		16	12	Block 1	325.00	9.00	20.00	30.00	5		
For Help, press Fl											





















